


515 Somerville Avenue Somerville, Massachusetts



August 11, 2020

Site History

- ▶ 1900 to 1924 – Residential
- ▶ 1924 to 1950 – Automotive Repair Shop/Gas Station
- ▶ 1950 to 1972 – Eastern Overall Company
 - ▶ Uniform supply and cleaning company
- ▶ 1972 to 2002 – Cutting/Seaming Textiles for Sports Apparel
- ▶ 2002 to Present – Vacant

Current Site Activities



Regulatory History

► Release Tracking Numbers (RTNs)

► 3-4350

► 3-23606

► 3-28545

► 3-28548


► 3-28564

Permanent
Solution
Achieved

► 3-36184


► 3-36373

Open



Constituents of Concern (COCs)

- ▶ 3-23606
 - ▶ Asbestos Containing Material (ACM)
 - ▶ Polycyclic Aromatic Hydrocarbons (PAHs)
 - ▶ Petroleum Hydrocarbons
 - ▶ Volatile Organic Compounds (VOCs)
 - ▶ Metals
- ▶ 3-36184
 - ▶ Polychlorinated Biphenyls (PCBs)
- ▶ 3-36373
 - ▶ Petroleum Hydrocarbons




Response Actions

- ▶ Environmental Monitoring Plan
 - ▶ Dust Monitoring
 - ▶ Ambient Air Screening for VOCs



Response Actions

- ▶ Environmental Monitoring Plan
 - ▶ Dust Monitoring
 - ▶ Ambient Air Screening for VOCs
- ▶ RTN 3-23606
 - ▶ Upper 1.5' of clean soil cap material will be replaced with 1' of subbase material covered by 3.5" asphalt
- ▶ RTN 3-36184
 - ▶ PCB affected material excavated and removed off-site



Response Actions

- ▶ Environmental Monitoring Plan
 - ▶ Dust Monitoring
 - ▶ Ambient Air Screening for VOCs
- ▶ RTN 3-23606
 - ▶ Upper 1.5' of clean soil cap material will be replaced with 1' of subbase material covered by 3.5" asphalt
- ▶ RTN 3-36184
 - ▶ PCB affected material excavated and removed off-site
- ▶ RTN 3-36373
 - ▶ Tank cleaned, emptied, and removed off-site
 - ▶ Affected material will be excavated and removed off-site
 - ▶ Further assessment activities to be performed

